



The diagram shows a stepped shaft with four sections of different diameters. The dimensions for each section are as follows:

Section	Diameter (mm)	Length (mm)
1 (Leftmost, smallest)	11.2	0.440
2	23.4	0.160
3 (Shaded)	23.4	0.320
4 (Rightmost, largest)	23.4	0.920